TOUGHPAD

FZ-G1A (Windows 7 Professional SP1 64bit)
Installation Instructions for All FZ-G1 Drivers and Utilities

Order	Driver Type	File Name	Unpacked Directory	Installation Procedure	Dependencies	Version	Release Date	Required	Microsoft Signed	Comments
	Dashboard for Panasonic PC Update	dboardg1_v2.07l13gm00(forfz-g1non-jpn)_fzg1_1_win7_64_d134710.exe	c:\util2\dboardg1	pinstall.bat execution. Run as administrator.		V2.07L13G M00		Recommend	No	This new version of utility accepts 5M pixel rear camera.
	Camera Utility Update	pcam_v3.08l14m00_fzg1_1_win7_64_d134961.exe	c:\util2\pcam	pinstall.bat execution. Run as administrator.	Install "Camera Light Switch Utility" before installing "Relating application".(For Camera Light model.) Furthermore, the following software is necessary to operate the application program. System Interface Device Drivers Common Components for Panasonic PC Common Components for Panasonic	V3.08L14 M00		Recommend	No	This new version of utility accepts 5M pixel rear camera.
	WWAN Driver for MC7305 (for Eu) New	wwan_10_build3919(3.5.1308.3911)_win7_eu_wwanctrl_fzg1_1_win7_64_d135429.exe	c:\util2\drivers\wwan_10	pinstall.bat execution. Run as administrator.		Build3919(3.5.1308.3911)_Win7_EU_wwanctrl		Mandatory	Yes	Please install for WWAN(MC7305(EU)) models only.
	AirCard Watcher for MC7305 (for Eu) New	wwancm10_build3846(6.0.3846.7403)_mc7305_eu_fzg1_1_win7_64_d134794.exe	c:\util2\wwancm10	Run "c:\util2\wwancm10\Watcher_Panasonic_Q.msi".		Build3846(6.0.3846.7403)_MC7305_EU		Option	No	This utility is not installed in Panasonic factory image. Please install for WWAN(MC7305(EU)) models only.
	WWAN Driver for MC7305 (for Australia) New	wwan_11_build3919(3.5.1308.3911)_win7_au_wwanctrl_fzg1_1_win7_64_d135431.exe	c:\util2\drivers\wwan_11	pinstall.bat execution. Run as administrator.		Build3919(3.5.1308.3911)_Win7_Au_wwanctrl		Mandatory	Yes	Please install for WWAN(MC7305(Australia)) models only.
	AirCard Watcher for MC7305 (for Australia) New	wwancm11_build3846(6.0.3846.7403)_mc7305_au_fzg1_1_win7_64_d134795.exe	c:\util2\wwancm11	Run "c:\util2\wwancm11\Watcher_Panasonic_Q.msi".		Build3846(6.0.3846.7403)_MC7305_Au		Option	No	This utility is not installed in Panasonic factory image. Please install for WWAN(MC7305(Australia)) models only.
	Wireless Helper Service New	whelper_v1.00l12m00_fzg1_1_win7_64_d134765.exe	c:\util2\whelper	pinstall.bat execution. Run as administrator.		V1.00L12M00		Recommend	No	

Panasonic
ideas for life